US Environmental Protection Agency Region II EXPEDITED REMOVAL ASSESSMENT CRITERIA

Revised:11/22/99

SITE NAME	Gordon	Finishing Company	
Date of Report	3/13/02	Removal Eligible (yes/no)	
SITE ID No.		CERCLIS No.	
		RCRIS No.	

Location:{street, block, lot, city, county, state, zip code,Longitude, Latitude}	19 West State St., Johnstown, Fulton County		y, New York, 12095
Mailing Address			
Abandoned (date)	circa 1998		
EPA Investigators (Name & Phone #)	Mike Solecki, 732 906-6918	Date of Investigation	2/19-21/2002
State Investigators (Name & Phone #)		Date of State Response	
State Case No.	NRC Case		
ERNS Case No.		1	
State Referring Agency & State Referral date:			
Contact for Access to Property (facility, state, local) (phone #)	Mike Solecki, FOSC, USEPA		
Directions to site (narrative) (Enclose copy of map at end of report)	NYSThruway, exit 27, NYSRt. 30A North, to Johnstown, in Johnstown: make left onto NYSRt. 67 West thru town, turn RIGHT onto Market St., go approximately one block bear LEFT at "Y" on toWest State St. Site is Approximately one block on right (# 19)		
Access Agreement (Verbal, Written, None, Any problems gaining access? If so, was an attorney assigned for the site? EPA Attorney's name & phone number)	The City of Johnstown owns the site (aquired for back taxes in 2001) the Fire Chief, Steve Hart, requested our asstistance at the request of the mayor and town council.		

A. Site History (Short Narrative describing the origination of the site)



The site was a leather finishing operation only. The tanned leather was sent by tanneries for dying and polishing prior to going through final preparation for shipping to goods manufacturing facilities.

The previous owner was a former worker at one of the local tanneries. He decided that he could provide a service to the local tanneries by providing finishing services during peak season. The local tanneries were able to provide enough business during the rest of the year to keep the facility all year round but at a reduced capacity. When the tanneries began closing there was not enough business to maintain the operation he closed. The facility closed in 1999.

Apparently, the former owner is Terry Gordon and still lives in the Johnstown area and works as an hourly worker whenever and wherever he can find work.

B. Site Characteristics

1. Physical Location

1. Physical Location	·
Type of Site (Industrial, Commercial, residential etc.)	Industrail in a residential area
Current Operations	ABANDONED
Past Operations	LEATHER FINISHING
Nature of Neighborhood (industrial, commercial, rural, suburban. Describe the pedestrian and vehicular traffic, is it a highway, is the area deserted etc.)	Vehicular and pedestian traffic is fairly high during the day. School children pass the facility to and from school. There is an operating finishing company next door and a warehouse on the otherside. Single and double occupancy homes are located accross the street.

2. Physical Characteristics

Size of Property	appears to be about an acre in size	Number of Buildings	1
Size of Bldgs, number of floors, basement	the building has a half-deep be full-above ground stories	sement from	street level, has 3
Building Drains (describe any evidence of potential discharge from the building and direction of flow, e.g sanitary sewer, are drain outfalls directed to a stream or other sensitive area, etc.)	The building has the normal sanitary connections, no floor drains were found however an extensive search was not conducted. The building is situated approximately 20 feet from the Cayadutta Creek (the creek is the back property boundry). A storm drain intake is located near the front of the building at the curb.		rch was not mately 20 feet pack property
Building Construction (Roof: Wood, metal Walls: Masonry, wood Floor: Concrete, wood)	The structure is basially wood	throughout.	
Fire Protection systems	The building has an out of service sprinkler system.		system.

Space availability for vehicles	staging areas are available on the property
trailers, staging of drums,	
equipment, etc.	⟨>

3. Site Conditions

Structural Integrity of	structural integrity is fair, bad stair ways, some floor
Building/Structures	openings, some water damage, low overheads
(e.g. holes in the roof, past fires,	
evidence of past damage, water	
damage, obstacles to site entry)	·
Evidence of Public Entry	No evidence of vagrents, etc yet, however the fire chief
(graffiti, vagrants, dumping etc.)	believes the it is only a matter of time once word gets out
Housekeeping	although the facility in messy, w/debris, it does not
(Evidence of stains on ground,	appear that there was any spillage, etc.
discolored water, pools of liquid on	
the ground, debris)	
Occupancy (hours occupied)	N/A
Utilities	All utilities are OFF
Power/gas/water (On/off)	
Is there a fire hydrant nearby?	
Lighting	Portable lighting will be necessary
(need of portable lights in order to	
work in the affected area?)	
Natural Hazards	It DOES NOT appear that there are any natural hazards
(e.g. poison ivy, poisonous snakes,	however the ERA was done in the dead of winter
stray dogs)	
Other hazardous substance	There were no obvious HS indicators other than the
indicators	drums
(e.g. Dead fish, animals, vegetation;	
fissures or cracks in solid surfaces	
to expose deep waste layers, cleared	
land areas, pits, possible landfilled	
areas, pools of liquids, distinct	
odors, anything unusual)	

4. Security

Fencing	There is no fencing .
(complete, partial, type, number of gates)	
Condition of fences (holes in fence)	
Other means of site access (open door, windows etc)	the door is padlocked, widows are not inaccessable
Security Guard/Service (Type, shift hours)	

5.Migration Pathways and Potential Receptors

Sewers (Storm or sanitary and distance from site)	on site
Waterway, Confluences, Water intakes, drinking water wells (Distance from site)	on stream bank of the Cayadutta Creek
Sensitive ecosystems (wetlands, sanctuaries etc. and distance from site)	just creek
Human Exposure (playground, nursing homes, schools etc., Distance from site)	None in the immediate area however it is a common route to the several schools
Air Pathways (Dust or spray in the air, asbestos, gas generation or effervescence, distinct odors,	Appear to be none, except in close proximity to drums

6. Instrumentation and Sampling

Significant instrument readings during investigations (List instrument, levels and background)	the standard air readings were taken and 120ppm was indicated in close proximity to sodium hydroxide drums and no reading exceeded 50ppm at any other containers (bare in mind that the ERA was done in dead of winter, not optimal for most volatils)
Number of samples and type of analysis (e.g. hazcat or lab)	51 samples were analyzed via HAZCAT and was performed on site by the Atlantic Strike Team; 25 liquid and 15 solid samples were sent to an independent lab for QA-1 analysisRESULTS PENDING

7. Number & Types of Containers

Container	Number and types of	Condition of containers
	Containers (eg. plastic, wooden, concrete, metal)	(rusted leaking, bulging corroded etc.)
55-gal drums	12 poly, 11 fibre, 1 steel	fair, some open
5 - 30 gal containers	30 g: 1 poly, 1 steel 1 fibre; 25 g: 15 fibre; 20 g: 1 fibre, 2 steel; 10 g: 2 steel; 8g: 1 poly; 5 g: 5 poly;	various stages, some have no covers
<5 gal containers	3 g: 6 poly; 1 g: 9 poly.	various stages, some have no covers
Below ground storage tanks (number and sizes; indicate phase levels, etc.)	None found	
Above ground storage tanks (number and sizes; indicate phase levels, etc.)	None found	
Secondary containment (Condition, size and type of construction)		
Other (cylinders, explosives, etc.)		
Empty containers (number, type and sizes)	40-55 g poly and fibre 80-5 g poly	•

8. Total Estimated Quantities

CERCLA Hazardous substance		
OIL	NONE	
RCRA		

9. Material Identification

Classification	Substance	Method of Identification (Labels, hazcat, analysis etc)
CERCLA (identify substances, e.g.benzene, PCB, etc.)	unknown organics, silicates, sodium hydroxide, salts, dyes containing metals, arsenic	HAZCAT, some labeled, final lab results pending
Oil (Type)	gasoline	·
RCRA hazardous waste		·

10. Evidence of Discharge

Evidence of actual discharge (leaking containers, observation of runoffs, etc.)	no apparent discharges
Potential discharge (Haphazard storage, incompatibility, etc.)	haphazard storage and a few incompatabilities were noted, incompatabilities were corrected
Imminent discharge (e.g.damaged drums located at the edge of waterway, etc.)	little potential discharges to the waterway

11. Pending Actions

Pending Actions to complete investigations	as of 3/26/2002 awaiting QA-1 lab results	
(e.g. sampling, hazcat, lab analysis)		

C. Site Legal Status

l. Ownership

Status of Site Ownership	City of Johnstown	
Status of Site Operations	abandoned	

2. Site Cleanup

Previous Actions	NONE	
Present Actions	NONE	•

3. Enforcement Actions:

Records (records at the site or elsewhere)	records appear intact and on site
Local	-
State	
EPA	
Other	

4. Suspected PRPs

Name	Address	Phone
Terry Gordon	UNK, Johnstown, NY	UNK
International Leather	UNK	UNK

E. Other Information

1. List of Contacts/ Other Notifications

Name	Affiliation	Address	Phone
		<u> </u>	
·			

2. Additional Information

3. Site Sketch, Maps, Photographs (append)

